r r 0 C r 0 D m eEr m Time Type | L # | Hits Search Text DBs f ro е Stamp i rs n n t i 8 t i 0 n USPA Т; EPO; 2003/06/1 1 BRS L1 2146 ceramic adj honeycomb 0 JPO; 3 18:06 DERW ENT USPA Т; EPO; 2003/06/1 2 BRS 667 1 and cordierite L2 0 JPO; 3 18:06 DERW ENT USPA Τ; EPO; 2003/06/1 2 and (partition adj 3 BRS L3 48 0 wall) JPO; 3 18:52 DERW ENT USPA Т; EPO; 2003/06/1 4 BRS L4 14 3 and pore 0 JPO; 3 18:07 DERW ENT USPA Τ; 6 and (pore adj EPO; 2003/06/1 5 BRS **上**7 2 0 volume) JPO; 3 18:08 DERW ENT USPA T; EPO; 2003/06/1 6 BRS L6 3 5 and rough\$4 0 JPO; 3 18:08 DERW ENT

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	ErrorDefinition	
7	BRS	L5	14			2003/06/1 3 18:09			0
8	BRS	L8 .	34	3 not 5		2003/06/1 3 18:21			0
9	BRS	L9	1	"6048490".PN.	USPA T	2003/06/1 3 18:45			0
10	BRS	L10	1	"6048490".PN.	USPA T	2003/06/1 3 18:46			0
11	BRS	L11	1	"5938992".PN.	USPA T	2003/06/1 3 18:47			0
12	BRS	L12	1	"5409870".PN.	USPA T	2003/06/1 3 18:49			0
13	BRS	L13	1	"5258150".PN.	USPA T	2003/06/1 3 18:49			0
14	BRS	L14	1	"4295892".PN.	USPA T	2003/06/1 3 18:50			0
15	BRS	L15	1	"5916511".PN.	USPA T	2003/06/1 3 18:50			0
16	BRS	L1.6	1	"5409870".PN.	USPA T	2003/06/1 3 18:51			0
17	BRS	L17	1	"5262102".PN.	USPA T	2003/06/1 3 18:51			0
18	BRS	L18	1	"5258150".PN.	USPA T	2003/06/1 3 18:51			0
19	BRS	L19	1	"5030398".PN.	USPA T	2003/06/1 3 18:51			0

Ì

	Type	L #	Hits	Search Text	DBs	Time Stamp	m m e n	Errorpefinition	Er ro rs
7	BRS	L7	0	ngk-insulator-ltd.as.	USPA T; EPO; JPO; DERW ENT	2003/06/1 5 12:06			0
8	BRS	L8	20536	ngk-insulators-ltd.as	USPA T; EPO; JPO; DERW ENT	2003/06/1 5 12:06			0
9	BRS	L9	591	3 and 8		2003/06/1 5 12:06			0
10	BRS	L11	2	10 and (thin adj wall)		2003/06/1 5 12:07			0
11	BRS	L10	41	9 and cordierite	USPA T; EPO; JPO; DERW ENT	2003/06/1 5 12:07			0